





CERTIFICATE

Reference:- Your office memo No. 4029-35/23 dated 01/05/2023.

"TO WHOM IT MAY CONCERN"

Undersigned inspected school building of GMSSSS, Raipur Rani, Panchkula. During the inspection of site, rooms of Block A & B visually appears unsafe for holding classes and rest of the blocks are safe for holding classes for the session 2023-24. The building was not constructed by this department, therefore our Department does not give any certificate regarding safety from earthquakes.


Sub Divisional Engineer,
Provincial Sub Division No.I,
Hr. PWD B&R Panchkula


Executive Engineer,
Provl. Divn., Hr.PWD B&R ,
Panchkula